



		art.	L mm				
	001100810	110BA 100	100	13	39	8,9	33
	001100815	110BA 150	150	18	49	12,2	33
	001100820	110BA 200	200	24	58	15,0	275
	001100825	110BA 250	250	30	60	18,2	505
	001100830	110BA 300	300	36	63	19,0	770
	001100837	110BA 375	375	46	66	24,5	1500
*	001100845	110BA 450	450	55	120	26,7	2261
*	001100860	110BA 600	600	65	155	36,0	4705



Werkzeug anwenden in einer hochdruck- oder hochgeschwindigkeitsschweißanlage ist gefährlich und kann zu ernsthaften Verletzungen führen.
 L'uso di questo strumento in presenza di corrente elettrica può provocare gravi lesioni.
 This equipment must never be used in contact with explosive or with other fire hazard materials.
 Aaparaat niet inzet bij het lassen of bij het werken onder andere omstandigheden met vlamgevaar.

